

**The result of the bidding for the procurement of Pipeline Induction Bends (Lot-A) under package-2: Procurement of Induction Bends, Different types of Valves, Pig Traps, Miscellaneous Fittings, CP Materials, Coating and Wrapping Materials for 36" OD High Pressure Gas Transmission Pipeline.**

**IFB No: 28.14.0000.174.02.003.16/25, Date: 04 October, 2016**

Bidder No.	Name of Bidders	Technical & Financial Responsiveness	Readout Price	Evaluated Price (Equivalent BDT)	Ranking	Remarks/Reasons of Rejection
1/6.	SUNGIL Co. Ltd., Korea	Technically & Financially Responsive	USD 3,340,055.00	26,24,61,521.90	1 <sup>st</sup> Lowest	NOA has been issued to the bidder on 16/3/2017.
2/6.	TECTUBI RACCORDI SPA, Italy	Technically Non Responsive	--	--	--	Non responsive due to: (i) Failure to comply with the required contractual experience criteria. (ii) Failure to meet the cash flow requirements. (iii) Failure to comply with the required delivery and completion schedule.
3/6.	Engie Fabricom, Belgium	Technically Non Responsive	--	--	--	Non responsive due to: (i) Failure to comply with the required contractual experience criteria. (ii) Failure to meet the cash flow requirements. (iii) Failure to comply with the required delivery and completion schedule. (iv) Failure to comply with GCC Clauses 9 & 17 of Section 7.
4/6.	S S Enterprise and Trading Consultants PTE LTD, Singapore	Technically Non Responsive	--	--	--	Non responsive due to: (i) Failure to comply with the required contractual experience criteria. (ii) Failure to meet the average annual turnover and cash flow requirements.
5/6.	Cangzhou Longtaidi Pipe Technology Co., Ltd., China	Technically & Financially Responsive	USD 3,509,677.00	27,57,90,418.66	2 <sup>nd</sup> Lowest	--
6/6.	JSC Trubodetal, Russia	Technically & Financially Responsive	USD 6,688,965.11	52,56,18,878.34	3 <sup>rd</sup> Lowest	--

**The result of the bidding for the procurement of Ball Valves, Plug Valves and Gate Valves (Lot-B) under package-2: Procurement of Induction Bends, Different types of Valves, Pig Traps, Miscellaneous Fittings, CP Materials, Coating and Wrapping Materials for 36" OD High Pressure Gas Transmission Pipeline.**

**IFB No: 28.14.0000.174.02.003.16/25, Date: 04 October, 2016**

Bidder No.	Name of Bidders	Technical & Financial Responsiveness	Readout Price	Evaluated Price (Equivalent BDT)	Ranking	Remarks/Reasons of Rejection
1/8.	Camtech Manufacturing FZCO, U.A.E	Technically Non Responsive	--	--	--	Non responsive due to: (i) Failure to comply with the required contractual experience criteria.
2/8.	TIV VALVES SRL, Italy	Technically & Financially Responsive	EURO 1,319,761.73	11,02,13,302.07	2 <sup>nd</sup> Lowest	--
3/8.	MIR VALVE SDN. BHD., Malaysia	Technically Non Responsive	--	--	--	Non responsive due to: (i) Failure to provide Delivery and Completion Schedule as per instruction stipulated therein. (ii) Failure to comply with the required contractual experience criteria. (iii) Failure to comply with the required technical experience criteria. (iv) Failure to provide acceptable authorization as per ITB 22.2 of the Bidding Document.
4/8.	Rotex Manufacturers & Engineers Pvt. Ltd., India	Technically Non Responsive	--	--	--	Non responsive due to: (i) Failure to comply with the required contractual experience criteria. (ii) Failure to comply with the required technical experience criteria.
5/8.	Joint Venture of Lishui Ouyi Valve Co., Ltd. and Oviko Group Co., Ltd., China	Technically Non Responsive	--	--	--	Non responsive due to: (i) Failure to comply with the required contractual experience criteria. (ii) Failure to meet the average annual turnover and cash flow requirements. (iii) Failure to provide Delivery and Completion Schedule as per instruction stipulated therein.
6/8.	VALVITALIA S.P.A, Italy	Technically Non Responsive	--	--	--	Non responsive due to: (i) Non submission of Bidding Forms to establish its qualification to perform the contract in accordance with Section 3. (ii) Failure to comply with the required contractual experience criteria. (iii) Failure to meet the average annual turnover and cash flow requirements. (iv) Proposal of liquidated damage of maximum 5% instead of 10% of the contract price and Failure to comply with GCC Clauses 27 of Section 7.
7/8.	Samjin JMC Co., Ltd., Korea	Technically Non Responsive	--	--	--	Non responsive due to: (i) The Bid wasn't accompanied by callable bid security as per ITB 21 of the Bidding Document as the submitted irrevocable letter of guarantee from Woori Bank, Korea wasn't endorsed by any schedule Bank of Bangladesh. (ii) Failure to comply with the required contractual experience, technical experience and production capacity criteria. (iii) Failure to meet the cash flow requirements.
8/8.	SICHUAN KCON VALVE MFG. CO., LTD., China	Technically & Financially Responsive	USD 1,209,503.08	9,50,42,752.02	1 <sup>st</sup> Lowest	NOA has been issued to the bidder on 09/03/2017.

*[Handwritten signature]*

*[Handwritten signature]*

*[Handwritten signature]*

*[Handwritten signature]*